Notification of Hazardous Waste Site United States **Environmental Protection** Agency ington DC 20460 formation is Please type or print in ink, If you need additional space, use separate sheets of) of the Compre-TLD022-15 sponse, Compenpaper. Indicate the letter of the item 1980 and must which applies. 810609 iLS-000-001-335 IL #253 Person Required to Notify: U. S. Industrial Chemicals Company Name Enter the name and address of the person P. O. Box 218 or organization required to notify. Street Tuscola IL 61953 City Zip Code Site Location: U. S. Industrial Chemicals Company Name of Site Enter the common name (if known) and actual location of the site. 3 miles west of U.S. 45 on U.S. 36 Street Zip Code 61953 120005078126 Tuscola Douglas Person to Contact: Plant Manager Tadler, Thomas Name (Last, First and Title) Enter the name, title (if applicable), and business telephone number of the person 217-253-3311 Phone to contact regarding information submitted on this form. **Dates of Waste Handling:** Enter the years that you estimate waste mid-1970 's 1953 From (Year) To (Year) treatment, storage, or disposal began and ended at the site. Waste Type: Choose the option you prefer to complete Option I: Select general waste types and source categories. If Option 2: This option is available to persons familiar with the Resource Conservation and Recovery Act (RCRA) Section 3001 you do not know the general waste types or sources, you are encouraged to describe the site in Item I--Description of Site. regulations (40 CFR Part 261). General Type of Waste: Place an X in the appropriate Source of Waste: Specific Type of Waste: Place an X in the appropriate EPA has assigned a four-digit number to each hazardous waste listed in the regulations under Section 3001 of RCRA. Enter the boxes. The categories listed boxes. appropriate four-digit number in the boxes provided. A copy of overlap. Check each applicable the list of hazardous wastes and codes can be obtained by category. contacting the EPA Region serving the State in which the site is located. 1. Ø Organics 1. Mining 2. M Inorganics 2. Construction 3. D Solvents 3. Textiles 4. Fertilizer 4. Pesticides 5 Heavy metals 5. ☐ Paper/Printing 6 DI Acids 6. Leather Tanning 7. I fron/Steel Foundry 7. Bases 8. D PCBs 8. D Chemical, General 9. Mixed Municipal Waste 9. Plating/Polishing 10. D Unknown 10. ☐ Military/Ammunition 11. ☐ Other (Specify) 11. Electrical Conductors 12. Transformers 13. Utility Companies 000114 JUN-881 14. ☐ Sanitary/Refuse 15. Photofinish 16. Lab/Hospital

Form Approved OMB No. 2000-0138 EPA Form 8900-1

1881 S 1 NUE


EPA Region 5 Records Ctr.

311007


17. Unknown

18. ☐ Other (Specify)

	Notification of Hazardous Waste Site	Side Iwo						
F.	Waste Quantity:	Total Facility Waste Amount						
	Place an X in the appropriate boxes to	1. D Piles	cubic feet Unknown					
	indicate the facility types found at the site.	2. Land Treatment	asllane	• , 1				
	In the "total facility waste amount" space give the estimated combined quantity	3. tX Landfill 4. □ Tanks	g					
	(volume) of hazardous wastes at the site using cubic feet or gallons.	5. 🖒 Impoundment	Total Facility Area square feet					
	In the "total facility area" space, give the	6. Underground Injection						
	estimated area size which the facilities	- · · · · · · · · · · · · · · · · · · ·		ximately 40				
	occupy using square feet or acres.	8. ☐ Drums, Below Ground 9. ☐ Other (Specify)	, ,					
	<u> </u>							
G	Known, Suspected or Likely Releases to the Environment: Place an X in the appropriate boxes to indicate any known, suspected, or likely releases of wastes to the environment.							
	Note: Items Hand I are optional. Completing hazardous waste sites. Although completing			n locating and assessing				
Н	Sketch Map of Site Location: (Option	al)						
	Sketch a map showing streets, highways, routes or other prominent landmarks near the site. Place an X on the map to indicate							
	the site location. Draw an arrow showing the direction north. You may substitute a publishing map showing the site location.	See Attachment	1 - USGS Map of	General Area				
			and					
		Attachment	t 2 ~ Facility Drawing					
ı	Description of Site: (Optional) Describe the history and present conditions of the site. Give directions to the site and describe any nearby wells, springs, lakes, or housing. Include such information as how waste was disposed and where the waste came from. Provide any other information or comments which may help describe the site conditions.	were used to store an aqueous 25 to 50% spent sulfuric acid solution from approximately 1953 until the mid 1970's, but						
		We have no known records to confirm that other materials were discarded into these pits; however, we suspect various substances (waste insulation, catalysts, miscellaneous solyents, etc.) may have been introduced prior to converting the impoundment areas to landfills with a slightly alkaline fly ash.						
	Signature and Title:							
	The person or authorized representative (such as plant managers, superintendents, trustees or attorneys) of persons required to notify must sign the form and provide a	V, S, Industrial Cf Street P. O. Box 218	emicals Co,	Ø Owner, Present □ Owner, Past □ Transporter				
	mailing address (if different than address in item A). For other persons providing notification, the signature is optional.	city Tuscola state I	☐ Operator, Present☐ Operator, Past					
	Check the boxes which best describe the relationship to the site of the person required to notify. If you are not required to notify check "Other".	Signature Rockley	Date 4/8/8/	Other				



ATTACHMENT 2
U. S. Industrial Chemicals Co. Facility Drawing



SCALE : 7/3" = 1000'

EPA ID# TL-D005078126												
SITE NAME U.S. Industrial Chemicals Co.												
NORLING FACTOR (>15 PTS.=HIGH MITRE POTENTIAL)												
NONDING THOTON		(> 15 1	isnight.	MIIKE I	OIENTIAL)							
WASTE TYPE		OUANTIT		cu.ft.:	=4 drums =	220	021c \					
PESTICIDES (5)						220	Ears.)					
HEAVY METALS (5)	TONS					PTS.						
PCB's (5)			·	>3500	>192,500	(5)						
ORGANICS (4)	875	437	11,799	3500	192,500							
SOLVENTS (4)	251	126	3,402	1001	55,055	(4)						
INORGANICS (3)	250	125	3,375	1000	55,000	(2)						
ACIDS (3) BASES (3)	163	82 81	2,214 2,187	651 650	35,805 35,750	(3)						
MIXED MUNI-WASTES (2)	76	38	1,026	301	16,555	(2)						
UNKNOWN (2)	75	37	999	300	16,500	(2)						
. /2/	21	11	297	81	4,455	(1)						
	<20	<10	<270	<80	<4,400	(0)	}					
FACILITY TYPE PILES DRUMS BELOW GROUND (4) DRUMS ABOVE GROUND (3) SURFACE IMPOUNDMENTS (3) TANKS LANDFILLS LAND TREATMENT (2) UNDERGROUND INJECTION (1) POPULATION 10,00C or more (5) 3,000 - 9,999 (4) 1,000 - 2,999 (3) 101 - 999 (2) 1 - 100 (1)												
NOT A HAZARDOUS WASTE INFORMATION MISSING COMMENTS:												
REVIEWER: Cathy F.												

U.S.INDUSTRIAL CHEMICALS CO.

Division of National Distillers and Chemical Corporation • P.O. Box 218, Tuscola, Illinois 61953 • (217) 253-3311

June 8, 1981

U. S. EPA Region 5 Sites Notification Chicago, Illinois 60604

Dear Sir:

Attached is completed Form 8900-1, Notification of Hazardous Waste Site, for U. S. Industrial Chemicals Company at Tuscola, Illinois.

Very truly yours,

Nadely.

T. J. Tadler Plant Manager

jw

Enclosure


T. J. Tadler, Plant Manager

U.S. INDUSTRIAL CHEMICALS CO.

P. O. Box 218, Tuscola, IL 61953



EN- 3-20M-10/79





U. S. EPA Region 5 Sites Notification Chicago IL 60604

